RURAL MUNICIPALITY OF MORRIS

No. 152

MORRIS, MANITOBA

Box 518, R0G 1K0 Ph: (204) 746-2642

RGE. 2 W.P.M. | RGE. 1 W.P.M. | RGE. 1 E.P.M. | RGE. 2 E.P.M.

TWP. 6 | TWP. 5 | TWP. 4

WP. 6 | WP. 5 | WP. 4

DUFFERIN OF R.M. | ROLAND OF R.M. | RHINELAND OF R.M. | MacDONALD OF R.M. | DE SALABERRY OF R.M. | RITCHOT OF R.M. | MONTCALM OF R.M.

WARNING - CALL BEFORE DIGGING (Shannon Olson 1-204-588-0388 - OIL PIPELINE)

WARNING - CALL BEFORE DIGGING (Shannon Olson 1-204-588-0388 - OIL PIPELINE)

WARNING - CALL BEFORE DIGGING (Shannon Olson 1-204-588-0388 - OIL PIPELINE)

RM MORRIS LANDFILL

RM MORRIS LANDFILL

councillor's request was checked; 1100mm x 20m & 900mm x 20m

Golf Course, New Site numbers, from Sites 233 to 244.

Sperling | Rosenort | Silver Plains | Aubigny | Union Point | Lowe Farm | Smith | Kane | McTavish | MORRIS

LEGEND:

Crown Land	C
Crown Leased Land	(CROWN)
Provincial Park	
Wildlife Management Area	W M A
Canada Mortgage and Housing Corp	C M H C
Farm Credit Corporation	F C C
Manitoba Agricultural Credit Corporation	M A C C
Residence	•
Earth Road	
Gravel Road	
Provincial Road	(67)
Provincial Trunk Highway	(1)

Revised DECEMBER 2009

SCALE IN KILOMETRES 0 1 2 3 4 5

SCALE IN MILES 0 1/2 1 2 3

LEGEND

AS	Additional Site
	Limestone In Progress
	Limestones Complete
	Ditch Cleaning In Progress
	Ditch Cleaning Completed
XXX	Site Complete
XXX	Culvert Complete
XXX	Engineer Report (ER) Site
XXX	Engineer Report (ER); Temporary Repaired
XXX	Culvert Needs Replacement
XXX	Regular Site (Ditch Cleaning and Roadwork

Culvert Replacement / Limestones Completed

Limestones In Progress

Ditch Cleaning Completed

Culvert / Ditch Cleaning In Progress

SMALL PARCEL INDEX

SEC 17 TWP 5 RGE 1 EPM

SEC 18 TWP 5 RGE 1 EPM

SEC 19 TWP 5 RGE 1 EPM

SEC 20 TWP 5 RGE 1 EPM

SEC 22 TWP 4 RGE 2 WPM

SEC 23 TWP 4 RGE 2 WPM

SEC 27 TWP 4 RGE 2 WPM

SEC 28 TWP 4 RGE 2 WPM

SEC 32 TWP 4 RGE 2 WPM

SEC 16 TWP 5 RGE 1 EPM

SEC 20 TWP 4 RGE 2 WPM

SEC 21 TWP 4 RGE 2 WPM

SEC 22 TWP 5 RGE 1 EPM

SEC 23 TWP 5 RGE 1 EPM

SEC 27 TWP 5 RGE 1 EPM

SEC 28 TWP 5 RGE 1 EPM

SEC 29 TWP 5 RGE 1 EPM

SEC 31 TWP 5 RGE 1 EPM

SEC 32 TWP 5 RGE 1 EPM

SEC 25 TWP 5 RGE 2 WPM

SEC 26 TWP 5 RGE 2 WPM

SEC 27 TWP 5 RGE 2 WPM

SEC 34 TWP 5 RGE 2 WPM

SEC 35 TWP 5 RGE 2 WPM

SEC 36 TWP 5 RGE 2 WPM

SEC 1 TWP 6 RGE 1 WPM

SEC 2 TWP 6 RGE 1 WPM

SEC 3 TWP 6 RGE 1 WPM

SEC 4 TWP 6 RGE 1 WPM

SEC 5 TWP 6 RGE 1 WPM

SEC 6 TWP 6 RGE 1 WPM

SEC 7 TWP 6 RGE 1 WPM

SEC 8 TWP 6 RGE 1 WPM

SEC 9 TWP 6 RGE 1 WPM

SEC 10 TWP 6 RGE 1 WPM

SEC 11 TWP 6 RGE 1 WPM

SEC 12 TWP 6 RGE 1 WPM

SEC 13 TWP 6 RGE 1 WPM

SEC 14 TWP 6 RGE 1 WPM

SEC 15 TWP 6 RGE 1 WPM

SEC 16 TWP 6 RGE 1 WPM

SEC 17 TWP 6 RGE 1 WPM

SEC 18 TWP 6 RGE 1 WPM

SEC 19 TWP 6 RGE 1 WPM

SEC 20 TWP 6 RGE 1 WPM

SEC 21 TWP 6 RGE 1 WPM

SEC 22 TWP 6 RGE 1 WPM

SEC 23 TWP 6 RGE 1 WPM

SEC 24 TWP 6 RGE 1 WPM

SEC 25 TWP 6 RGE 2 WPM

SEC 26 TWP 6 RGE 2 WPM

SEC 27 TWP 6 RGE 2 WPM

SEC 28 TWP 6 RGE 2 WPM

SEC 29 TWP 6 RGE 2 WPM

SEC 30 TWP 6 RGE 2 WPM

SEC 31 TWP 6 RGE 2 WPM

SEC 32 TWP 6 RGE 2 WPM

SEC 33 TWP 6 RGE 2 WPM

SEC 34 TWP 6 RGE 2 WPM

SEC 35 TWP 6 RGE 2 WPM

SEC 36 TWP 6 RGE 2 WPM

PROMAP
638-3584 Fax: (204) 638-3386
repromap@repromap.com
www.repromap.com
er South - P.O. Box 778 - Dauphin, MB R7N 3E3

NOTE:
THIS MAP IS PROTECTED BY COPYRIGHT
UNAUTHORIZED REPRODUCTION IS PROHIBITED
NOT RESPONSIBLE FOR ANY ERRORS OR OMISSIONS